

**AUTHORIZATION OF CONTRACTS FOR ADVERTISEMENT**

Contract No. 1803, "Repairs to Fluid Bed Incinerator No. 2"

This contract will provide for any repairs that may be uncovered during an upcoming internal inspection of Fluid Bed Incinerator No. 2. Likely issues may include plenum and shell cracks and manifold warping, erosion or cracking.